Patch note

1. Added the option to control a deformation scale.
   : Optimized deformation shape for small deformations can be displayed.

2. Priority of member type changed when creating drawings.

  : (Before) flat slab > beam --> (After) beam > flat slab

3. Fixed an error that generated an unnecessary information of plate element when exporting nGen models to Gen

4. Fixed an error that the change a length unit was not considered when calculating "n_s" according to Thailand code.

5. Fixed an error with a curved walls not showing normally.

6. Fixed an error that the meshed shape was not generated normally after an opening is not moved.

7. Fixed an error that p-delta results and remarks were output with wrong value in the stability Coefficient table.

[Drawing]

1. Fixed the error that did not drawing the information of additional bar in the basement wall.

2. Fixed an error that total length was not calculated normally.